



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program September 3, 2008

Reviewed: 

Mine Name: TD Mining	Permit Number: M0270080
Operator Name: David Peterson	Inspection Date: 07/17/2008
Inspector(s): Tom Munson	Time: 3:00PM
Other Participants:	Mine Status: active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Re-vegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: **Bond Amount:** \$11,000 **Permit fee** is delinquent since 2007

Purpose of Inspection:


To determine the status of the site. It has been inactive since 2002.

Inspection Summary:

Arrived on site to find no new disturbance but the metal silo, metal screen, roads, existing pits and pads that were abandoned in 2002 are still on site. In conversation with the BLM, they are going to inspect the site and determine if it is appropriate to revoke the reclamation bond.

Conclusions and Recommendations:

The operator has failed to pay permit fees for the years of 2007 and 2008. The site has been abandoned since 2002. The Division needs to send a letter to the operator requesting past due fees and reclamation based on over five years of suspended operations. The BLM holds \$11,000 reclamation bond.

Inspector's Signature 

TM:pb

cc: (OPERATOR)

jerry_mansfield@blm.gov

O:\M027-Millard\M0270080-TD Mining\inspections\insp-07172008.doc

